NTSB ID: FTW02LA105 Aircraft Registration Number: N29795

Occurrence Date: 03/28/2002 Most Critical Injury: Minor

Occurrence Type: Accident Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Buena Vista	СО	81211	0828	MST	
Airport Proximity: On Airport	Distance Fror	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	210-M	Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 28, 2002, at 0828 mountain standard time, a Cessna 210-M airplane, N29795, registered to and operated by a private individual, was substantially damaged when it impacted the runway shortly after take off from runway 33 at the Central County Municipal Airport, Buena Vista, Colorado. The airline transport rated pilot and one of his passengers were not injured and his second passenger received minor injuries. Visual meteorological conditions prevailed and a flight plan was not filed for the Title 14 Code of Federal Regulations Part 91 personal flight. The local flight was originating at the time of the accident.

In a telephone interview with the NTSB investigator-in-charge, the pilot stated that after liftoff the airplane was at about "fifty to one-hundred feet off the ground when it was suddenly knocked to the ground." He stated that he maintained directional control as the airplane impacted the runway "hard." The pilot, who had accumulated over 1,500 hours in the same make and model reported that the airplane encountered an unexpected downdraft.

NTSB ID: FTW02LA105

Occurrence Date: 03/28/2002

AVIATION Occurren					ence Type: Accident								
Landing Facility/Approach Inf	formation												
Airport Name	- Cimation		Airpo	ort ID:	Airport Eleva	tion	Run	way Used	Runwa	ay Lengt	th	Run	way Width
Central Colorado Reginal			7V1		l '	7980 Ft. MSL 33 8300		8300			75		
Runway Surface Type: Asphalt							<u> </u>						
Runway Surface Condition: Dry													
Type Instrument Approach: Unknown	own												
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer				Model/	/Series					Serial	Numbe	er	
Cessna				210-N	И					2106	2114		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Retractable - Tricycle													
Homebuilt Aircraft? No	Number of Se	ats: 4		Certified Max Gross Wt.				3800 LBS Numb			per of Engines: 1		»: 1
				Engine Manufacturer: Model/Series: TSIO-520-R					Rated Power: 315 HP				
- Aircraft Inspection Information			•	·									
Type of Last Inspection			Date of Last Inspection Time S			Time Si	Since Last Inspection				Airframe Total Time		
Annual			08	08/2001 179 H					lours 3658 Hours			3658 Hours	
- Emergency Locator Transmitter (ELT) Information	n								•			
ELT Installed? Yes	ELT Op	erated? No	0	ELT Aided in Locating Accident Site? No									
Owner/Operator Information													
Registered Aircraft Owner			Street Address 31211 Northwoods Circle										
Robert D. Schork			City								Sta	te	Zip Code
			Buena Vista CO 81. Street Address								81211		
Operator of Aircraft			Same as Reg'd Aircraft Owner										
Same as Reg'd Aircraft Owner			City							Sta	te	Zip Code	
Operator Does Business As:							Ol	perator Desi	gnator Co	ode:		<u>'</u>	
- Type of U.S. Certificate(s) Held: N	None												
Air Carrier Operating Certificate(s):													
Operating Certificate:			Operator 0	Certific	cate:								
Regulation Flight Conducted Under	r: Part 91: Ge	neral Avia	ition										
Type of Flight Operation Conducted	l: Personal												
		FACT	UAL.	REPO	RT - AVIATI	ION							Page 2

NTSB ID: FTW02LA105

Occurrence Date: 03/28/2002

AVIATION				Occurrence Type: Accident									
First Pilot	Information	,,											
Name						City				Sta	ate	Date of Birth	Age
On File				On File					On	File	On File	50	
Sex: M	Seat Occupied	: Left	Prin	cipal Profes	sion: Busin	ess				Certifica	ite Num	ber: On File	•
Certificate(s): Fligh	nt Instructor	; Private						·				
Airplane Ra	ating(s): Mult	i-engine Laı	nd; Single-eı	ngine Land									
Rotorcraft/Glider/LTA: None													
Instrument Rating(s): Airplane													
Instructor Rating(s): Airplane Multi-engine													
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 05/2000													
Medical Cert.: Class 2 Medical Cert. Status: Valid Medicalw/ waivers							n.		Date of	Last M	ledical E	Exam: 09/2001	
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	t	Ins Actual	Instrument Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time													
Pilot In Cor	nmand(PIC)												
Instructor													
Last 90 Da	ys												
Last 30 Da										\rightarrow			
Last 24 Ho	urs	<u> </u>				 							
Seatbelt Us	sed? Yes	Shou	ılder Harness	Used? Yes			Toxicology Performed? No Second Pilot? No						0
Flight Pla	n/Itinerary												
	ht Plan Filed: N	one											
Departure F							State	Aiı	port Ident	ifier	Depa	arture Time	Time Zone
Same as	Accident/Incide	ent Location						7\			0828		MST
Destination	1						State	Air	port Iden	ifier			
Same as	Accident/Incide	ent Location	l						7V1				
Type of Cle	earance: None					_							
Type of Air	space: Class	E											
Weather	Information												
Source of		cord of briefi	ing										
Method of	Briefing: Unkno	own											
				FACTUAL	REPORT	- AVIA	TION						Page 3

NTSB ID: FTW02LA105

Occurrence Date: 03/28/2002

Occurrence Type: Accident

	FTYBOR			/	710010011								
Weather Information WOE ID Charactics Time Time Time WOE Flowting WOE Flowting WOE Flowting Time Accident Site Provided From Accident Site													
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	WOF Distance From Accident Site Direction From Accident Site)	
7V1	0825	MST	7980 Ft.	MSL	NM Deg. M						Mag.		
Sky/Lowes	st Cloud Condition: Few			9000 Ft. AGL					Condition of Light: Day				
Lowest Ce	eiling: None		Ft.	AGL	Visibi	ility:	30	SM	Altir	meter:	30.00	"Hg	
Temperatu	ure: 12 °C	Dew Point:	-9 °C	Wind	Direction:	260			Der	nsity Altitude:		Ft.	
Wind Spee	∍d: 15	Gusts: 27		Weath	ner Condti	ions at Ac	cident S	Site: Visual C	Cond	itions			
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	y of Precip	oitation:						
Restriction	Restrictions to Visibility: None												
Type of Pro	Type of Precipitation: None												
Accident	Information												
Aircraft Da	mage: Substantial		Aircraft Fire	e: None	e Aircraft Explos					osion None			
Classificati	ion: U.S. Registered/U	.S. Soil											
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	ır	None	TOTAL							
First Pi	ilot				1		1						
Second	d Pilot						\neg						
Studen	nt Pilot						7						
Flight I	Instructor						٦						
Check	Pilot						ヿ						
Flight E	Engineer						Π ニ						
Cabin /	Attendants						Π ニ						
Other C	Crew						7						
Passen	ngers			1	1		2						
- TOTAL /	ABOARD -			1	2		3						
Other 0	Ground						٦						
- GRANE	O TOTAL -			1	2		3						

National Transportation Safety Board

FACTUAL REPORT AVIATION

Occurrence Date: 03/28/2002

Occurrence Type: Accident

							-			
/\	dm	ını	Ctr	つけい	10	Int	10ri	സവ	tιΛ	n
$\overline{}$	um	11 11	อแ	au	/ =	11111	OH	III a	แบ	ш

Investigator-In-Charge (IIC)

Alexander Lemishko

Additional Persons Participating in This Accident/Incident Investigation:

Jim Hopkins Air Safety Inspector FAA FSDO Denver, CO